

Welding Inspection Handbook



American Welding Society®

Welding Inspection Handbook

**Fourth Edition
2015**

**Prepared by the
AWS B1C Standing Task Group on Welding Inspection Handbook**

**Under the Direction of the
AWS Technical Activities Committee**

**Approved by the
AWS Board of Directors**



American Welding Society®

ISBN: 978-0-87171-855-6

© 2015 by American Welding Society
All rights reserved
Printed in the United States of America

THE WELDING INSPECTION HANDBOOK is a collective effort of many volunteer technical specialists to provide information to assist welding inspectors and supervisors in the technology and application of visual and nondestructive examination.

Reasonable care is taken in the compilation and publication of the *Welding Inspection Handbook* to ensure authenticity of the contents. However, no representation is made as to the accuracy or reliability of this information, and an independent substantiating investigation should be undertaken by any user.

The information contained in the *Welding Inspection Handbook* shall not be construed as a grant of any right of manufacture, sale, use, or reproduction in connection with any method, process, apparatus, product, composition, or system, which is covered by patent, copyright, or trademark. Also, it shall not be construed as a defense against any liability for such infringement. Whether or not use of any information in the Handbook would result in an infringement of any patent, copyright, or trademark is a determination to be made by the user.

Personnel

AWS B1C Standing Task Group on Welding Inspection Handbook

U. Aschemeier, Chair	<i>Subsea Global Solutions LLC</i>
E. Abrams, Secretary	<i>American Welding Society</i>
B. Baker	<i>Bechtel National, Incorporated</i>
R. Campbell	<i>Banker Steel Company</i>
R. Clarke	<i>TEAM Industrial Services</i>
R. Cook	<i>SME Steel Contractors</i>
G. Gratti	<i>Arcos Industries LLC</i>
E. Lichtfusz	<i>Roush Industries</i>
C. Mankenberg	<i>Shell International Exploration & Production</i>
J. Mehta	<i>Alta Vista Solutions</i>
A. Moore	<i>Marion Testing & Inspection</i>
H. Thompson	<i>UL LLC</i>

Special Contributor

W. Komlos	<i>Arc Tech LLC</i>
-----------	---------------------

Foreword

The inspection of welds and welded assemblies requires knowledge of many factors of welding quality control. This includes dimensional inspection, nondestructive examination methods, welding processes, welding metallurgy, destructive testing, and the qualification of welding procedures and personnel. It also includes the examination and test requirements of codes, criteria, and specifications; the acceptance standards to be employed; and an understanding of drawings, and welding and nondestructive examination symbols. Knowledge about discontinuities that may be associated with different welding processes, and the ability to evaluate the difference between discontinuities and rejectable defects, is also an important element of welding inspection.

This fourth edition of the *Welding Inspection Handbook* has been prepared by the AWS B1C Welding Inspection Handbook Task Group. The objective is to provide a reliable source of useful reference information. This is particularly relevant for the technically trained individual who may not be directly involved with inspection but whose position requires knowledge about welding inspection. This book also is intended for the inspector who needs a general refresher in the basic requirements of weld inspection. This fourth edition supersedes the AWS *Welding Inspection Handbook* bearing the same title, and includes changes to numerous clauses to provide clarification, correct inconsistencies, and updates representative of current industry practices.

Underlined text in the clauses and subclauses indicates a change from the 2000 edition. A vertical line in the margin indicates a revision from the 2000 edition.

Additional books on the subjects covered in each chapter may be found in good technical libraries. The many specifications and codes that have been used as examples may also be consulted for more detailed information.

This book is an instructive reference. Codes or specifications applicable to any particular weldment always take precedence over the generalized material contained herein. The text of this book has, of necessity, been written in general terms and cannot include all the conditions applicable to a specific instance. Thus, examples given are general and are used only for the purpose of illustration.

Every effort has been made to present this material in convenient form so that the book can be used as a training text for inspectors, engineers, and welders. Although the information generally relates to the arc welding processes, most of it applies to any weldment—fabricated by any joining process—for which the inspection methods described herein may be required.

For the inspection of brazed assemblies, refer to *The Brazing Handbook* published by the American Welding Society. For the inspection of resistance welded assemblies, refer to AWS/SAE D8.7, *Recommended Practices for Automotive Weld Quality—Resistance Spot Welding*, also published by the American Welding Society.

Information on nondestructive examination methods is available in AWS B1.10M/B1.10, *Guide for Nondestructive Examination of Welds*, and in AWS B1.11M/B1.11, *Guide for the Visual Examination of Welds*.

Comments and inquiries concerning this publication are welcome. They should be sent to the Managing Director, Technical Services Division, American Welding Society, 8669 NW 36 St, # 130, Miami, FL 33166.

Contents

Chapter	Page
<i>Personnel</i>	iii
<i>Foreword</i>	v
<i>List of Tables</i>	viii
<i>List of Figures</i>	ix
1 Scope and Application	1
2 Symbols.....	3
3 Requirements for the Welding Inspector.....	13
4 Welding Inspection Operations	21
5 Inspection Safety Considerations.....	27
6 Quality Assurance	33
7 Ferrous Welding Metallurgy	37
8 Preheating and Postweld Heat Treating	53
9 Weld and Weld Related Discontinuities.....	57
10 Qualification of Welding Procedure Specifications	75
11 Qualification of Welders and Welding Operators	91
12 Computerization of Welding Inspection and Quality.....	103
13 Destructive Testing of Welds	111
14 Proof Tests.....	137
15 Nondestructive Examination Methods	141
16 Qualification of Nondestructive Examination Personnel.....	239
17 Codes and Other Standards	241
18 Metric Practice	255
Index.....	267

List of Tables

Table		Page
4.1	Sequence of Welding and Inspection Operations	24
10.1	Welding Procedure Specification and Welder Qualification Factors Which May Require Requalification	81
13.1	Typical Hardness Conversion Table (Approximate) (for Carbon and Low-Alloy Steels in Accordance with ASTM E140 and ASTM A370).....	120
15.1	Considerations when Selecting an NDE Method.....	143
15.2	Radiographic Isotopes Used in Industrial Radiography	155
15.3	Approximate Radiographic Equivalence Factors of Several Metals.....	157
15.4	Resistivity and Conductivity of Some Metals and Alloys	218
18.1	SI Base and Supplementary Units and Symbols	255
18.2	SI Derived Units and Symbols	256
18.3	SI Factors, Prefixes, and Symbols.....	256
18.4	Units Not Part of the SI System	257
18.5	SI Unit Conversion Factors	258
18.6	General Conversion Factors	258
18.7	Commonly Used Metric Conversions (Inch–Millimeter Conversion).....	262
18.8	Pressure and Stress Equivalents—psi and ksi to kPa and MPa.....	263
18.9	Conversions for Fahrenheit–Celsius Temperature Scales	264

List of Figures

Figure	Page
2.1	AWS Standard Welding Symbols 4
2.2	Comparison of Welding Symbol and Written Explanation..... 6
2.3	Examples of Typical Fillet Welds Showing the Corresponding Symbols and Dimensions 7
2.4	Examples of Typical Groove Welds Showing the Corresponding Symbols and Dimensions 8
2.5	Standard Location of Elements for NDE Symbols 9
2.6	Examples of Typical Nondestructive Examination Symbols 9
2.7	Master Chart of Welding, Allied Processes, and Thermal Cutting 10
<u>5.1</u>	<u>SDS Sheet</u> 28
<u>7.1</u>	<u>Iron-Carbon Phase Diagram</u> 38
7.2	Crystal Structure of Cold Rolled Steel in Weld Area 39
7.3	Martensite Showing Needle-Like or Acicular Structure (500X Before Reduction)..... 40
7.4	Example of Delayed Cracking in HAZ..... 42
7.5	Corrosion Attack of Sensitized Stainless Steel in Acid Environment 46
7.6	Microfissure in Austenitic Stainless Steel (100X) 47
7.7	Closeup of Lamellar Tear Under a Fillet Weld Showing Typical Stepped Appearance (Magnification 8X) 48
9.1	Typical Distortion of Welded Joints..... 59
9.2	Overlap..... 61
9.3	Weld Sizes 61
9.4	Incomplete Joint Penetration and Incomplete Fusion 63
<u>9.5</u>	<u>Underfill</u> 65
<u>9.6</u>	<u>Various Types of Cracks</u> 66
<u>9.7</u>	<u>Porosity</u> 70
10.1	AWS Structural Welding Code, <u>Welding Procedure Example Form</u> 79
10.2	<u>Example of a Suggested Procedure Qualification Record (PQR)</u> 86
10.3	ASME <u>Welding Procedure Qualification Record Example Form</u> 88
11.1A	Test Plate for Unlimited Thickness—Welder Qualification 93
11.1B	Optional Test Plate for Unlimited Thickness—Horizontal Position—Welder Qualification 93
11.2A	Tubular Butt Joint—Welder Qualification—Without Backing 94
11.2B	Tubular Butt Joint—Welder Qualification—With Backing 94
11.3A	Positions of Groove Welds 95
11.3B	Positions of Fillet Welds 96
11.4	Positions of Test Plates for Groove Welds 97
11.5	Positions of Test Pipe or Tubing for Groove Welds 98
11.6	Positions of Test Plate for Fillet Welds 99
11.7	Positions of Test Pipes for Fillet Welds 100

11.8	Suggested Form for Welding Performance Qualification	101
12.1	A Welding Inspection Database	105
13.1	Typical Photomicrographs	114
13.2	Photomicrograph Illustrating the Appearance of a Crack in the Heat-Affected Zone (Approximately 100X).....	114
13.3	Photomicrographs	115
13.4	Typical Stress-Strain Diagram Used in the Offset Method.....	121
13.5	Standard Tension Specimens.....	123
13.6A	Transverse Face- and Root-Bend Specimens.....	126
13.6B	Transverse Side-Bend Specimens	127
13.7	Fixture for Guided Bend Test.....	128
13.8A	Transverse Rectangular Tension Test Specimen (Plate)	130
13.8B	Longitudinal Rectangular Tension Test Specimen (Plate).....	131
13.9	Typical Fillet Weld Break and Macroetch Test for Fillet Welder or Welding Operator Qualification	132
13.10	Charpy (Simple-Beam) Impact Test Specimens	134
13.11	Charpy (Simple-Beam) Impact Test.....	135
15.1	Welding Engineer Data Sheet	146
15.2	<u>Rulers, Measuring Tapes</u> , and Gauges for Checking Fitup and Weld Dimensions	147
15.3	Weld Bead Contours	148
15.4	Workmanship Standard	149
15.5	Sketches of Weld Undercut and Overlap	150
15.6	Photographs of Weld Undercut and Overlap.....	151
15.7	Weld Inspection Gauges.....	152
15.8	Typical “Shadow Graph”	154
15.9	The Penumbral Shadow	158
15.10	Geometric Principles of Shadow Formation.....	159
15.11	Factors Affecting Quality of Radiographic Image.....	162
15.12	Sources of Scattered Radiation	164
15.13	Characteristic Curve For a Typical Industrial X-Ray Film	166
15.14	The “Tools of The Trade” for the Radiographer	169
15.15	Typical Penetrameter Design	170
15.16	Typical Radiographic Exposure Arrangements	172
15.17	Typical Radiographs of Weld Discontinuities.....	177
15.18	Block Diagram, Pulse-Echo Flaw Detector	179
15.19	Decibel-To-Screen Height or Voltage Nomograph	181
15.20	Snell’s Law of Reflection and Refraction	183
15.21	Amplitude Calibration Using Flat Bottom Holes	185
15.22	Shear Wave Ultrasonic Beam.....	185
15.23	Amplitude Calibration.....	186
15.24	Ultrasonic Ruler Application	190
15.25	Flaw Orientation.....	191
15.26	Sound Beam Propagation Showing Sound Path Distance	191
15.27	Magnetic Field in a Bar Magnet	194
15.28	Magnetic Field in a Bar Magnet That Has Been Cut in Half.....	195
15.29	Magnetism Around a Notch Cut in a Bar Magnet	196

15.30	Magnetic Field Around a Conductor Carrying Current	197
15.31	Field of Ferromagnetic Conductor is Confined Almost Entirely to the Conductor Itself.....	197
15.32	Magnetic Particles Near a Defect are Attracted to the Local Poles	197
15.33	In Large Parts, Local Areas Can Be Magnetized; Arrows Indicate Field.....	198
15.34	Part to be Inspected Can Be Magnetized by Making it the Core of a Solenoid.....	199
15.35	Crack in Large Plate is Indicated by Alignment of Particles Between Prods	200
15.36	Dry Powder Magnetic-Particle Inspection of Welds with Portable Equipment	202
15.37	Wet Fluorescent Magnetic-Particle Inspection to Show Fine Surface Defects	203
15.38	Typical Indication of Surface Crack in a Weld	207
15.39	Indication of a Subsurface Crack in a Weld (The Dry Magnetic Particles Assume a Less Defined Pattern).....	208
15.40	Liquid Penetrant Comparator.....	213
15.41	Frequencies Used for Various Test Problems	215
15.42	Cross-Sectional View of a Bar with a Small Crack, Surrounded by an Exciting Coil and a Pickup Coil, Showing Eddy Current Distribution.....	216
15.43	Relative Conductivity of Metals and Alloys Related to Eddy Current Meter Readings	217
15.44	Influence of Impurities on the Conductivity of Pure Copper.....	219
15.45	Typical B/H (Hysteresis) Curve	220
15.46	Lines of Magnetic Flux Surrounding a Solenoid	220
15.47A	Instrumentation Readout for Electromagnetic Testing	221
15.47B	Typical Eddy Current Readout from Strip Chart Illustrating Good and Bad Weld Areas	221
15.48	Production of Eddy Currents by an Alternating Field	222
15.49	Testing Coils Carrying Alternating Current	223
15.50	Examples of Electromagnetic Probe Coils.....	224
15.51	Eddy Current Strength Drops Off With Distance From Surface	224
15.52	Eddy Current Flaw Detection Equipment	225
15.53	Microstructure of Austenitic Weld Specimen	232
15.54	Schaeffler Diagram for Stainless Steel Weld Metal.....	233
15.55	DeLong Diagram for Stainless Steel Weld Metal	234
15.56	Typical Flow Diagram from Contract to Approved Operations Procedures.....	235

Chapter 1

Scope and Application

1.1 Scope

The scope of this handbook includes testing and examination methods that apply to a majority of metallic and nonmetallic weldments used in construction. The extent of inspections should be clearly defined in contract documents or on drawings that refer to a particular weldment (unless otherwise defined in applicable codes or specifications). Furthermore, acceptance criteria should be clearly understood and agreed upon by both the supplier and the purchaser before any production welding begins. Acceptance criteria for weld discontinuities are specifically excluded from this handbook.

It is the responsibility of those charged with the administration and supervision of inspection to make certain that the principles and methods to be used are properly understood and applied uniformly. This responsibility may include the qualification and certification of inspectors where such certification is required by codes, specifications, job contracts, civil law, or company policies.

The following documents address the qualification of welding inspection and nondestructive examination personnel:¹

- (1) AWS QC1, *Standard for AWS Certification of Welding Inspectors*
- (2) AWS B5.1, *Specification for the Qualification of Welding Inspectors*
- (3) ANSI/ASNT CP-189, *ASNT Standard for Qualification and Certification of Nondestructive Testing Personnel*
- (4) ASNT Recommended Practice SNT-TC-1A, *Personnel Qualification and Certification in Nondestructive Testing*
- (5) ASTM 1316, *Standard Terminology for Nondestructive Testing*
- (6) ISO 9712, *Nondestructive Testing—Qualification and Certification of NDT personnel*

Even when a particular qualification for certification program is not mandatory, every welding inspector should be aware of the ethical criteria for welding inspectors contained in documents such as AWS QC1.

1.2 Application

The information in this handbook pertains to the general duties and responsibilities of welding inspectors and is intended as a reference to help their performance. This book provides specific information about methods of weldment inspection; however, much of the information will also generally apply to the examination of nonwelded components, such as base metal inspection prior

1. See Chapter 17 for addresses of standards writing organizations.