



**APPROVED METHOD:  
GUIDE TO GONIOMETER  
MEASUREMENTS AND TYPES, AND  
PHOTOMETRIC COORDINATE SYSTEMS**  
AN AMERICAN NATIONAL STANDARD



**ANSI/IES LM-75-19**

**APPROVED METHOD:  
GUIDE TO GONIOMETER MEASUREMENTS AND TYPES,  
AND PHOTOMETRIC COORDINATE SYSTEMS  
AN AMERICAN NATIONAL STANDARD**

Publication of this document  
has been approved by the IES.  
Suggestions for revision  
should be directed to the IES.



*Copyright 2019 by the Illuminating Engineering Society.*

*Approved by the IES Standards Committee, May 15, 2019, as a Transaction of the Illuminating Engineering Society.*

*Approved November 22, 2019 as an American National Standard.*

*All rights reserved.* No part of this publication may be reproduced in any form, in any electronic retrieval system or otherwise, without prior written permission of the IES.

Published by the Illuminating Engineering Society, 120 Wall Street, New York, New York 10005.

IES Standards and Guides are developed through committee consensus and produced by the IES Office in New York. Careful attention is given to style and accuracy. If any errors are noted in this document, please forward them to Brian Liebel, Director Standards, at [standards@ies.org](mailto:standards@ies.org) or the above address for verification and correction. The IES welcomes and urges feedback and comments.

Printed in the United States of America.

ISBN #978-0-87995-010-1

---

## DISCLAIMER

IES publications are developed through the consensus standards development process approved by the American National Standards Institute. This process brings together volunteers representing varied viewpoints and interests to achieve consensus on lighting recommendations. While the IES administers the process and establishes policies and procedures to promote fairness in the development of consensus, it makes no guaranty or warranty as to the accuracy or completeness of any information published herein.

The IES disclaims liability for any injury to persons or property or other damages of any nature whatsoever, whether special, indirect, consequential or compensatory, directly or indirectly resulting from the publication, use of, or reliance on this document.

In issuing and making this document available, the IES is not undertaking to render professional or other services for or on behalf of any person or entity. Nor is the IES undertaking to perform any duty owed by any person or entity to someone else. Anyone using this document should rely on his or her own independent judgment or, as appropriate, seek the advice of a competent professional in determining the exercise of reasonable care in any given circumstances.

The IES has no power, nor does it undertake, to police or enforce compliance with the contents of this document. Nor does the IES list, certify, test or inspect products, designs, or installations for compliance with this document. Any certification or statement of compliance with the requirements of this document shall not be attributable to the IES and is solely the responsibility of the certifier or maker of the statement.

## AMERICAN NATIONAL STANDARD

Approval of an American National Standard requires verification by ANSI that the requirements for due process, consensus, and other criteria have been met by the standards developer.

Consensus is established when, in the judgment of the ANSI Board of Standards Review, substantial agreement has been reached by directly and materially affected interests. Substantial agreement means much more than a simple majority, but not necessarily unanimity. Consensus requires that all views and objections be considered, and that a concerted effort be made toward their resolution.

The use of American National Standards is completely voluntary; their existence does not in any respect preclude anyone, whether that person has approved the standards or not, from manufacturing, marketing, purchasing, or using products, processes, or procedures not conforming to the standards.

The American National Standards Institute does not develop standards and will in no circumstances give an interpretation to any American National Standard. Moreover, no person shall have the right or authority to issue an interpretation of an American National Standard in the name of the American National Standards Institute. Requests for interpretations should be addressed to the secretariat or sponsor whose name appears on the title page of this standard.

CAUTION NOTICE: This American National Standard may be revised at any time. The procedures of the American National Standards Institute require that action be taken to reaffirm, revise, or withdraw this standard no later than five years from the date of approval. Purchasers of American National Standards may receive current information on all standards by calling or writing the American National Standards Institute.

**Prepared by:  
The IES Testing Procedures Committee**

**Becky Kuebler, *Chair***  
**Andrew Jackson, *Vice-Chair***  
**David N. Randolph, *Secretary***  
**Jian Zhong Jiao, *Treasurer***

**Members**

C. K. Andersen	K. C. Fletcher	M. Kotrebai	C. Miller
R. P. Bergin	M. L. Grather	J. E. Leland	E. Radkov
R. S. Bergman	Y. H. Hiebert	S. Longo	M. B. Sapcoe
E. Bretschneider	J. Hospodarsky	J. P. Marella	J. E. Walker
P. Elizondo	J. N. Hulett	P. McCarthy	
D. J. Ellis	P.-C. Hung	G. McKee	

**Advisory Members**

L. M. Ayers	J. Frazer	J. Lockner	A. W. Serres
J. Baker	K. J. Hemmi	Y. Ohno	G. A. Steinberg
C. A. Bloomfield	S. Hua	E. Page	L. Swainston
P.-T. Chou	G. John	D. Park	J. S. Swiernik
M. Damle	H. Kashaninejad	E. S. Perkins	A. Thorseth
L. Davis	T. Kawabata	M. Piscitelli	R. C. Tuttle
J. J. Demirjian	R. Kelley	D. Rogers	J. C. Vollers
M. E. Duffy	K. C. Lerbs	M. Royer	Y. Zong
V. Eberhard	K. M. Liepmann	T. Schneider	

---

# CONTENTS

<b>Foreword</b> .....	<b>1</b>
<b>1.0 Introduction and Scope</b> .....	<b>1</b>
1.1 Introduction.....	1
1.2 Scope .....	1
<b>2.0 Normative References</b> .....	<b>1</b>
<b>3.0 Definitions, including spherical coordinates</b> .....	<b>1</b>
3.1 apolar angle.....	1
3.2 attitude, application .....	2
3.3 attitude, design .....	2
3.4 attitude, measurement.....	2
3.5 azimuth angle.....	2
3.6 CIE (A, $\alpha$ ) Coordinate System .....	2
3.7 CIE (B, $\beta$ ) Coordinate System .....	2
3.8 CIE (C, $\gamma$ ) Coordinate System .....	2
3.9 circumpolar angle (azimuth angle) .....	2
3.10 coordinate system.....	2
3.11 datum axis .....	2
3.12 datum half-plane.....	3
3.13 elevation angle.....	3
3.14 first axis (of a light source).....	3
3.15 frame of reference.....	3
3.16 frame of reference, application.....	3
3.17 frame of reference, goniometer .....	3
3.18 frame of reference, laboratory .....	3
3.19 frame of reference, source.....	3
3.20 half-plane of data .....	3
3.21 half-plane, goniometric .....	3
3.22 handedness (of a coordinate system).....	3
3.23 IES Coordinate System A (Y, X).....	3
3.24 IES Coordinate System B (H, V) .....	4
3.25 IES Coordinate System C (V, L) .....	4
3.26 left-handed coordinate system.....	4
3.27 light source .....	4
3.28 photometric center (of a light source) .....	4

3.29	planar angle (angle in plane)	4
3.30	right-handed coordinate system	4
3.31	second axis (of a light source)	4
3.32	spherical coordinates	4
3.33	test axis (of a source)	5
3.34	third axis (of a light source)	5
3.35	tilt, measurement (of a source)	5
3.36	zenith angle	5
<b>4.0</b>	<b>Laboratory, Goniometer, and Source frames of reference</b>	<b>5</b>
4.1	Frames of Reference Applicable to Goniophotometry	5
4.1.1	Source Frame of Reference	5
4.1.2	Goniometer Frame of Reference	6
4.1.3	Laboratory Frame of Reference	6
4.1.4	Application Frame of Reference	6
4.2	Orientation with Respect to Gravity	6
<b>5.0</b>	<b>Coordinate Systems</b>	<b>7</b>
5.1	Spherical Coordinate Systems	7
5.2	Defining a Spherical Coordinate System	7
5.3	Example: The Geographic Coordinate System	8
5.4	Standard Goniophotometric Coordinate Systems	9
5.4.1	IES Coordinate System A (IES-A)	9
5.4.2	IES Coordinate System B (IES-B)	10
5.4.3	IES Coordinate System C (IES-C)	10
<b>6.0</b>	<b>Goniophotometers</b>	<b>11</b>
6.1	Type A Goniophotometer	11
6.1.1	Instrument Design and Setup	11
6.1.2	Instrument Operation	11
6.1.3	Applications	12
6.2	Type B Goniophotometer	12
6.2.1	Instrument Design and Setup	12
6.2.2	Instrument Operation	12
6.2.3	Applications	13
6.3	Type C Goniophotometer	13
6.3.1	Instrument Design and Setup	13
6.3.2	Instrument Operation	14
6.3.3	Applications	14
6.3.4	Design Variations	14

<b>6.4</b>	<b>Type D Goniophotometer</b> .....	<b>16</b>
6.4.1	Instrument Design and Setup .....	16
6.4.2	Instrument Operation .....	16
6.4.3	Applications .....	16
<b>7.0</b>	<b>Calibration</b> .....	<b>16</b>
<b>7.1</b>	<b>Relative Photometry Method</b> .....	<b>16</b>
<b>7.2</b>	<b>Absolute Photometry Method</b> .....	<b>17</b>
7.2.1	Luminous Intensity Calibration .....	18
7.2.2	Illuminance Calibration .....	19
7.2.3	Total Luminous Flux Calibration .....	20
<b>8.0</b>	<b>Integrated Measurements</b> .....	<b>21</b>
<b>8.1</b>	<b>Method of Calculation</b> .....	<b>21</b>
<b>8.2</b>	<b>Angular Frequency of Data Points</b> .....	<b>21</b>
<b>9.0</b>	<b>Stray Light Elimination and Correction</b> .....	<b>22</b>
<b>9.1</b>	<b>Stray Light and Its Sources</b> .....	<b>22</b>
<b>9.2</b>	<b>Stray Light Elimination Techniques</b> .....	<b>22</b>
9.2.1	Limiting Field of View .....	22
9.2.2	Reducing Reflected Light .....	22
9.2.3	Use of a Light Trap .....	22
<b>9.3</b>	<b>Stray Light Correction Methodologies</b> .....	<b>22</b>
9.3.1	Using a Mask .....	23
9.3.2	Handling of Negative Luminous Intensity Values .....	23
<b>9.4</b>	<b>Stray Light and Uplight Measurement</b> .....	<b>23</b>
9.4.1	Uplight Detection Threshold .....	23
9.4.2	Criteria for Zeroing Uplight Readings .....	24
9.4.3	Stray Uplight Test Setup .....	24
9.4.4	Stray Uplight Test Procedure .....	25
<b>9.5</b>	<b>Reporting Zeroed Stray Uplight</b> .....	<b>25</b>
<b>Annex A</b>	<b>Coordinate System Conversion</b> .....	<b>26</b>
<b>Annex B</b>	<b>Zonal Constant Calculations</b> .....	<b>27</b>
<b>Annex C</b>	<b>Informative References</b> .....	<b>28</b>

## Foreword

---

This document is an update of LM-75-2001, which was reaffirmed in 2012. The document has been updated to reflect current use of goniophotometers in industry, including calibration methods and methodologies for correction of stray light. Updated in this document are definitions of goniophotometer types and coordinate systems for photometric measurement of light sources. This document supersedes any angular conventions presented in LM-72-1997. This document does not cover near-field goniometers.

## 1.0 Introduction and Scope

---

### 1.1 Introduction

A goniophotometer is a photometer for measuring the directional light distribution characteristics of sources, luminaires, media and surfaces. A goniophotometer records photometric readings at a series of spherical coordinates to define a web of photometric data surrounding the item under test. Goniophotometric data are presented using various angular coordinate systems, and acquired using instruments of various constructions. In addition to goniophotometers, goniospectrometers exist, which use three- or four-channel colorimeters to measure color properties at a series of spherical coordinates, and goniospectroradiometers exist, which use array spectrometers to measure spectral properties at a series of spherical coordinates. Historically, each type of goniophotometer was developed to measure a light source used in a specific application. Conventionally, measurement results for each type of light source were presented using a coordinate system that matched the specific application. Many current IES documents mention goniophotometers and coordinate systems. This document offers a complete explanation and provides harmonious definitions.

For luminaires, goniophotometers are used to measure luminous intensity distributions using either the relative or absolute photometry method. Using relative photometry, the luminous intensity in each direction is derived by normalizing the indicated

luminous intensity of the luminaire and then scaling it to the rated initial lumens of the bare lamp(s) used in the luminaire; thus, absolute photometric calibration of the goniophotometer is not necessary using this method. However, relative photometry does not work for certain solid-state lighting (SSL) products, where the source(s) cannot be separated from the luminaire. For such products, absolute photometry, which requires a calibrated goniophotometer, shall be used.

This document provides definitions of goniophotometer types, spherical coordinate systems, and a general guide to goniophotometer calibration. Definitions presented herein are generally consistent with those in corresponding CIE publications [CIE 102<sup>1</sup> and CIE 121<sup>2</sup>]. Differences or inconsistencies are noted.

### 1.2 Scope

This document provides definitions of spherical coordinate systems and goniophotometer types used to measure light sources. It does not address the use of goniophotometers to measure media or surfaces. The operating principles behind each type of goniophotometer are addressed, and a general guide to goniophotometer calibration, stray light elimination, and stray light correction is presented. A methodology for zeroing data when measuring upward light is also provided. In addition, the correspondences between relevant IES and CIE definitions are described.

## 2.0 Normative References

---

Illuminating Engineering Society. ANSI/IES RP-16-17, Nomenclature and Definitions for Illuminating Engineering. New York: IES; 2017. Online: [www.ies.org/standards/definitions/](http://www.ies.org/standards/definitions/). (Accessed 2019 Jul 26).

## 3.0 Definitions, Including Spherical Coordinates

---

### 3.1 apolar angle

In a spherical coordinate system,<sup>3,4</sup> an angle measured from the positive pole; with the circumpolar angle, one of two